MODULE IV - INDUSTRIAL WASTE LAGOON POST-CLOSURE CARE

IV.A. POST CLOSURE CARE

The Permittee shall conduct all post-closure care activities in accordance with the post-closure plan as specified in Attachment 1 and this permit, in compliance with R315-8-7.

The Permittee shall maintain and monitor the industrial waste lagoon, after completion of closure and corrective action activities, in compliance with R315-8-11 and R315-8-7 and this permit. The Permittee shall:

- **IV.A.1.** Maintain the integrity and effectiveness of the final cover in compliance with R315-8-11.5(b)(1) and Attachment 1 of the permit, including making repairs to the cap as necessary to correct the effects of settling, subsidence, erosion or other events.
- **IV.A.2.** Maintain and monitor the groundwater monitoring system and the groundwater treatment system in compliance with R315-8-11.5(b)(3), R315-8-6 and Module V and Module VI of this permit.
- **IV.A.3.** Prevent run-on and run-off from eroding or otherwise damaging the final cover in compliance with R315-8-11.5(b)(4).
- **IV.A.4.** Prohibit post-closure use of the property which will disturb the integrity of the final cover, containment systems, or monitoring system.
- **IV.A.5.** Protect and maintain surveyed benchmarks used.

IV.B. COST ESTIMATES FOR POST-CLOSURE CARE

As indicated by R315-8-8, states and the federal government are exempt from the requirements for post-closure care cost estimates.

IV.C. FINANCIAL ASURANCE FOR POST-CLOSUR CARE

As indicated by R315-8-8, states and federal government are exempt from the requirements for post-closure care financial assurance.

IV.D. INSPECTIONS

Inspections will be conducted during the post-closure care period in compliance with the procedures specified in Condition II.D. and as specified in Attachment 1. All records of inspections and remedial actions shall be retained in the Operating Record, as indicated by condition I.F.13.d, throughout the post-closure care period. Any deterioration or malfunction discovered by an inspection will be remedied in compliance with R315-8-2.6(d).